ÜRO Parts



HEAVY-DUTY ALUMINUM THERMOSTAT HOUSING

03H121117APRM | URO-012048 | 2007–2011 Audi, VW

OEM DESIGN FAULT

Modern plastic thermostat housings are prone to catastrophic failure after thermal cycling and exposure to oil or transmission fluid vapor. The embrittled plastic eventually ruptures, resulting in a major leak and dangerous overheating.

ÜRO PREMIUM SOLUTION

URO Parts has developed an aluminum thermostat housing for a truly robust repair, which is impervious to heat and underhood chemicals. This all-metal upgrade fixes the problem right the first time, and is covered by a lifetime warranty.