


PRODUCT UPDATE



The WIX 33783 fuel filter has undergone a design change. The center hole that was part of the former construction **is no longer required** for the new construction. Filtered water content coalesces on the outside of the media and drains down the side of the filter into the bowl to be drained as necessary.



The indexed indentations visible in the seamed area of the can are the result of the use of an alternate baseplate construction. The shape of this baseplate prevents the can from rotating independently of the threaded plate once the two are seamed. The process used to make this geometry also reduces overall metal waste which supports environmental waste reduction efforts. When seamed, the filter can conforms to the shape of the baseplate resulting in the indentations identified in the illustration. The indentations **should not be confused with dents or damaged seams.**