

WARNING

THREADED SENDING UNIT MUST BE
RETAINED. ENGINE MUST NOT BE
OPERATED UNTIL SENDING UNIT IS
SECURELY THREADED INTO THREADED
HOLE IN THE END OF THE FILTER.
FAILURE TO DO SO WILL RESULT IN
FUEL LOSS AND A POTENTIAL FIRE
HAZARD.

14-68749

PRINTED IN U.S.A.

4.000

4.000

NOTE:
PLAIN 20# WHITE BOND
PRINT WITH BLACK INK