ÜRO Parts



HEAVY-DUTY ALUMINUM COOLING HOSE FLANGE

06A121132CPRM | URO-011077 | 1998–2005 VW

OEM DESIGN FAULT

Plastic coolant flanges are prone to catastrophic failure after thermal cycles and exposure to oil, grease, or transmission fluid. The embrittled plastic eventually ruptures, resulting in a major leak and dangerous overheating.

ÜRO PREMIUM SOLUTION

URO Parts has developed an aluminum coolant flange for a truly robust repair, which is impervious to engine heat, motor oil and ATF. This fixes the problem right the first time, and is covered by a lifetime warranty.