ÜRO Parts



HEAVY-DUTY ALUMINUM ENGINE COOLANT PIPE

11537502525PRM | URO-007947 | 1998–2006 BMW

OEM DESIGN FAULT

BMW M52 six-cylinder engines utilize fragile plastic coolant pipes, which often deform and crack over time. The pipes must be periodically replaced to help prevent system rupture and costly engine damage due to rapid overheating.

ÜRO PREMIUM SOLUTION

URO has developed all-aluminum pipes for a reliable repair. With sturdy welded-metal mounting brackets, OE-style end fittings, quality EPDM seals, and a glossy black finish, URO Premium metal pipes permanently rectify OE plastic pipe deficiencies.