POWER DOOR LOCK ACTUATORS

WHAT'S IN YOUR BOX?

StandardWhatsInYourBox.com

Unlock Service Opportunities

All Standard® Power Door Lock Actuators are endurance tested for long-term durability and to meet Federal Motor Vehicle Safety Standards (FMVSS) for door ejection.

What's inside the Standard® box...
Extensive testing, precision engineering and over 100 years of experience.
What's In Your Box?™

We offer the most complete program in the aftermarket with over 1,100 Door Handle Repair Kits, Door Latch Assemblies, Hood Latch Assemblies, Power Door Lock Actuators, Tailgate Latch Assemblies, Tailgate Lock Actuator Motors and Trunk Lock Actuator Motors. When OE fails, trust Standard® to provide the highest quality replacement components for your customers' vehicles.



100%
TESTED & VALIDATED

100% tested and validated for long-term performance and durability

Manufactured using the highest quality components to meet federal safety requirements

INDUSTRY-LEADING COVERAGE

1,100+ Door Lock Actuators covering over 1 billion service opportunities

Standard® Precision-Engineered Power Door Lock Actuators

To ensure long-term durability and safety, Standard® Power Door Lock Actuators are precision engineered and extensively tested to meet federal safety requirements. All Standard® Power Door Lock Actuators are direct OE replacements for easy installation.

Meets Federal Standards
FMVSS (Federal Motor Vehicle Safety Standards) No. 206 requirements for door ejection safety

Accuracy
Designed and manufactured to OE specifications for a direct-fit replacement

Durability
Robust construction ensures long, trouble-free service life

Easy to Install
'Plug & Play' design means no wire splicing



DLA690
Power Door Lock Actuator
Toyota / Lexus
Cars, Trucks & SUVs
(2024-06) VIO: 13.6M

To increase customer satisfaction and reduce comebacks, you can recommend replacing the door lock actuator whenever you are servicing the interior door components on a higher mileage vehicle. This is especially true if a window lift motor has failed from moisture intrusion, an electrical issue or an impact.

For more than 100 years, when the OE failed, technicians have trusted Standard® and Blue Streak® to deliver a part that's equal to or better than the original it's replacing.

STANDARDBRAND.COM

STANDARDBLUESTREAK.COM

SMPCORP.COM

ST11804