GF10232B

Anti-Theft Notice

This product requires Anti-Theft Reprogramming Equipment for installation.

Please refer to a factory service manual for the procedures required to install and program this part. Failure to perform the required reprogramming may cause the vehicle not to start or function properly.

Avis – reprogrammation antivol

L'installation de ce produit exige l'utilisation d'équipement de reprogrammation antivol.

Veuillez consulter le guide de réparation du fabricant pour connaître les procédures d'installation et de programmation de cette pièce. La reprogrammation requise doit être effectuée, faute de quoi le véhicule pourrait ne pas démarrer ou ne pas fonctionner correctement.

Notificación sobre equipo anti-robo

Este producto requiere equipo de reprogramación anti-robo para la instalación.

Por favor consulte un manual de servicio de la fábrica para obtener los procedimientos requeridos para instalar y programar esta pieza. No realizar la reprogramación requerida puede causar que el vehículo no arranque o que funcione incorrectamente.